



⑦ 9-7-63

7. Major portion of Searle Marsh tract 20, camera facing east. Upper part of photo shows "horseshoe bend" in Crane Creek and major portion of Dewey tract no. 18. Almost entire dike system of Searle Marsh needs complete overhaul. A part of the dike cut out shortly after this picture was taken, and all of the water was lost. Light colored area (water) in upper left corner is Lake Erie at mouth of Crane Creek. North end of B & T, Inc., tract no. 19, shows in upper right corner of photo.