



10. Major portion of Willow Point Club tract no. 10, camera facing east. Eastern boundary (dike trail) of Pintail Marsh tract no. 11 crosses lower part of photo. Some riprap had to be placed along the dike in 1963, more will be needed to permanently secure the dike. Dike work will also be needed to permanently secure the Willow Point Marsh. The remains of old pier-pilings can be seen extending out into Lake Erie at top center. They are at the mouth of Crane Creek where some type of structure is needed to keep mouth of Creek open.