The Trail Inventory of Egmont Key National Wildlife Refuge Crystal River, FL



Prepared By: Federal Highway Administration Central Federal Lands Highway Division March, 2006





Egmont Key NWR Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

					Mileage by Trail Condition							Total	
Trail Surface	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	lated*	Miles
Type	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
Native	0.20	18%		0%		0%		0%		0%		0%	0.20
Gravel		0%		0%		0%		0%		0%		0%	0.00
Asphalt		0%		0%		0%		0%		0%		0%	0.00
Concrete	0.36	32%		0%	0.12	11%		0%		0%		0%	0.48
Turnpike		0%		0%		0%		0%		0%		0%	0.00
Boardwalk		0%		0%		0%		0%		0%		0%	0.00
Puncheon		0%		0%		0%		0%		0%		0%	0.00
Woodchips		0%		0%		0%		0%		0%		0%	0.00
Mowed		0%		0%		0%		0%		0%		0%	0.00
Admin Road		0%		0%		0%		0%		0%		0%	0.00
Other	0.45	40%		0%		0%		0%		0%		0%	0.45
Totals	1.01	89%	0.00	0%	0.12	11%	0.00	0%	0.00	0%	0.00	0%	1.13

Trail Miles and Percentages by Trail Classification and Condition

	Mileage by Trail Condition									Total			
Trail	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	ated*	Miles
Classification	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
TC1		0%		0%		0%		0%		0%		0%	0.00
TC2	0.20	18%		0%		0%		0%		0%		0%	0.20
TC3		0%		0%		0%		0%		0%		0%	0.00
TC4	0.81	72%		0%	0.12	11%		0%		0%		0%	0.93
TC5		0%		0%		0%		0%		0%		0%	0.00
Totals	1.01	89%	0.00	0%	0.12	11%	0.00	0%	0.00	0%	0.00	0%	1.13


^{*} Admin Roads are included in the inventory but are not rated for condition.

Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T400	Sign	8	Yes	N/A	51
T400	Sign	1	No	0.48	56
T400	Sign	1	No	0.73	65
T400	Sign	1	No	0.89	66
T400	Sign	1	No	0.90	67


sf-square feet If-linear feet cf-cubic feet

EGMONT KEY NATIONAL WILDLIFE REFUGE TRAIL LOCATION MAP









TRAILS ID

Station Name: Egmont Key NWR


Trail #	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T400	Historical Military Trail	Native, Concrete, Paver Block	10014656	1.13	From lighthouse to end of trail

Org. Code: 41562

TRAIL CONDITION

FCI

Condition



Trail Name: Historical Military Trail Refuge Name: Egmont Key NWR

Trail Number: T400 Region: 4 TOTAL LENGTH: 1.13 Miles Section Number 001 002 003 004 005 Section Length (miles) 0.12 0.16 0.26 0.03 0.36 **SAMMS Number** 10014656 10014656 10014656 10014656 10014656 Rating Date 3/16/2006 3/16/2006 3/16/2006 3/16/2006 3/16/2006 Trail Section Information TC4 TC4 TC4 TC4 TC4 Trail Class Paver Block Paver Block Paver Block Surface Type Concrete Concrete Surface Firmness Paved Paved Paved Paved Paved Width (inches) 118 160 160 160 160 Average Grade (%) 0.6 0.6 0.6 0.6 0.6 Average X-slope (%) 1.2 1.2 1.2 1.2 1.2 Trail Condition Information **Deferred Maintenance** \$3303 \$0 \$0 \$0 \$0 **CRV** \$32671 \$121311 \$195296 \$19152 \$140186

Trail Condition TOTALS

0

Excellent

Excellent

Excellent

0.101


Fair

Deferred Maintenance	CRV	FCI	Condition
\$3303	\$542527	0.006	Excellent

0

Excellent


TRAIL DEFICIENCY



Trail Name: Historical Military Trail Refuge Name: Egmont Key NWR

Trail Number: T400 Region: 4 TOTAL LENGTH: 1.13 Miles

Mile Post	0		
Section Number	001		
Photo Number	49		
Deficiency	Trail Structure		
Action	Repair		
Item	Tread -sf		
Quantity	1198		
Deferred Maintenance	\$3303		



Trail Name: Historical Military Trail Refuge Name: Egmont Key NWR

Trail Number: T400 Region: 4 TOTAL LENGTH: 1.13 Miles Section Number 006 Section Length (miles) 0.2

SAMMS Number 10014656 Rating Date 3/16/2006 Trail Section Information TC2 Trail Class Surface Type Native

Surface Firmness Firm Width (inches) 108 Average Grade (%) 0.6 Average X-slope (%) 1.2

Trail Condition Information

Deferred Maintenance \$0 **CRV** \$33911 FCI 0 Excellent Condition

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$3303	\$542527	0.006	Excellent

TRAIL NUMBER: **T400** STATION: Egmont Key NWR

DATE: 3/16/2006



Photo # 49 - MP 0.0 - Trailhead, Trail Structure Deficiency (Broken Concrete)

TRAIL NUMBER: **T400**

STATION: Egmont Key NWR



Photo # 51 - MP 0.11 - Sign (Grouped Feature)

TRAIL NUMBER: **T400** STATION: Egmont Key NWR

DATE: 3/16/2006



Photo # 50 - MP 0.12 - Begin Section 002

TRAIL NUMBER: **T400**

STATION: Egmont Key NWR



Photo # 56 - MP 0.48 - Sign

TRAIL NUMBER: **T400** STATION: Egmont Key NWR

DATE: 3/16/2006



Photo #64 - MP 0.7 - Begin Section 006

TRAIL NUMBER: **T400**

STATION: Egmont Key NWR



Photo # 65 - MP 0.73 - Sign

TRAIL NUMBER: **T400** STATION: Egmont Key NWR

DATE: 3/16/2006



Photo # 66 - MP 0.89 - Sign

TRAIL NUMBER: **T400**

STATION: Egmont Key NWR



Photo # 67 - MP 0.9 - Sign