The Trail Inventory of Mandalay NWR Houma, LA





Prepared By: Federal Highway Administration Central Federal Lands Highway Division March, 2012



TABLE OF CONTENTS

SECTION		<u>PAGE</u>
I.	TRAIL AND TRAIL FEATURE SUMMARIES	1 - 1
II.	TRAIL LOCATION MAPS	2 - 1
III.	TRAIL IDENTIFICATION LIST	3 - 1
IV.	TRAIL CONDITION RATING SHEETS	4 - 1
V.	TRAIL DEFICIENCY RATING SHEETS	5 - 1
VI.	PHOTOGRAPHIC SHEETS	6 - 1
VII.	GLOSSARY	i

Mandalay NWR

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface	Excel	lent	Total	
Туре	Miles	%	Miles	
Native	0.17	100%	0.17	
Gravel	0.26	100%	0.26	
Total	0.43	100%	0.43	

Trail Miles and Percentages by Trail Classification and Condition

Trail	Excel	lent	Total	
Classification	Miles	%	Miles	
тсз	0.43	100%	0.43	
Total	0.43	100%	0.43	

^{*}Admin Roads are included in the inventory but are not rated for condition.

Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T300	Trailhead	1	No	0.00	MAND_C2_00 05
T300	Bridge -sf	320	No	0.16	MAND_C2_00 06
T300	Begin Section	1	No	0.17	MAND_C2_00 07
T300	Boardwalk -If	44	No	0.24	MAND_C2_00 08
T300	Boardwalk -If	36	No	0.36	MAND_C2_00 09
T300	Lookout/Ob Deck	1	No	0.43	

sf - square feet

If - linear feet

cf - cubic feet

Mandalay NWR Trail Location Map




HQ/VC


Trails ID

Station Name: Mandalay NWR Org Code: 43626

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Nature Trail	Gravel	N/A	0.26	From Nature Trail Parking (Rte 901) to Observation Deck
T300	Nature Trail	Native	N/A	0.17	From Nature Trail Parking (Rte 901) to Observation Deck

TRAIL CONDITION





Trail Name:Nature TrailRefuge Name:Mandalay NWRTrail Number:T300Region: 4Total Length:0.43 Miles

Section Number	001	002
Section Length (miles)	0.17	0.26
SAMMS Number	N/A	N/A
Rating Date	03/25/2006	03/25/2006
Trail Section Information		
Trail Class	TC3	TC3
Surface Type	Native	Gravel
Surface Firmness	Firm	Soft
Width (inches)	112	60
Average Grade (%)	1.4	1.4
Average X-slope (%)	3.90	3.90
Trail Condition Information		
Deferred Maintenance		
CRV	\$31,186	\$27,873
FCI	0.00	0.00
Condition	Excellent	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$59,060	0.00	Excellent

TRAIL DEFICIENCY

No Deficiencies

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T300 STATION: Mandalay NWR DATE: 03/25/2006



Photo # MAND_C2_0005 - MP 0.00 - Trailhead

TRAIL NUMBER: T300 STATION: Mandalay NWR

DATE: 03/25/2006



Photo # MAND_C2_0006 - MP 0.16 - Bridge -sf

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T300 STATION: Mandalay NWR DATE: 03/25/2006



Photo # MAND_C2_0007 - MP 0.17 - Begin Section

TRAIL NUMBER: T300 STATION: Mandalay NWR

DATE: 03/25/2006



Photo # MAND_C2_0008 - MP 0.24 - Boardwalk -If

PHOTOGRAPHIC SHEET

TRAIL NUMBER: T300 STATION: Mandalay NWR

DATE: 03/25/2006



Photo # MAND_C2_0009 - MP 0.36 - Boardwalk -If

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS SAMMS number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI > - .20 = Failed

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

i

Elem ID Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped Features Grouped features include non-unique signs (mileposts,

interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity"

field of the data dictionary.

Info Type Type of accessibility information available at trailhead:

brochure, sign or other.

Item Item on which the "Action" (see above) will be

performed.

Manage_Use Managed use of the trail: HIKE, BIKE, NSPC (non-

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

MP Distance of a trail feature or deficiency from the

Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail Structure Boardwalk, Turnpike, Puncheon.

T Class Trail Class: I-V (see Appendix? for trail class

descriptions).

Tr Desig Trail Designation: Standard (Std), National Historic Trail

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Turnpike Trail tread elevated with dirt, rock or other aggregate

from parallel side ditches and held in place by logs.