The Trail Inventory of North Attleboro NFH

North Attelboro, MA





Prepared By: Federal Highway Administration Central Federal Lands Highway Division June, 2013



TABLE OF CONTENTS

SECTION		PAGE
I.	TRAIL AND TRAIL FEATURE SUMMARIES	1 - 1
II.	TRAIL LOCATION MAPS	2 - 1
III.	TRAIL IDENTIFICATION LIST	3 - 1
IV.	TRAIL CHANGES AND CONDITION RATING SHEETS	4 - 1
V.	TRAIL DEFICIENCY RATING SHEETS	5 - 1
VI.	PHOTOGRAPHIC SHEETS	6 - 1
IX.	GLOSSARY	i

NOTE TO USERS OR READERS

In this report, the reader may find a mix of dates associated with the condition assessment and photographs. Chapter 4 shows an updated condition assessment for each trail documented in this report. However there may be dates on the condition assessment pages that range from 2006 and 2007 to 2012. This occurred because the GPS dates of the trails originally rated in Cycle 1 were not updated when the cycle 3 assessment was done to in

2012. That GPS date is the basis for the Rating date in the report. Any new trail or section of trail that was collected and rated in Cycle 3 will have a rating date of 2012. While the rating dates may show a pre 2012 date, each trail was walked and its condition was assessed in 2012 during the Cycle 3 field season.

In Chapter 6 the reader may notice photographs with dates ranging from 2006 and 2007 to 2012. This occurs because the existing photographs from Cycle 1 were used if no significant or noticeable changes were seen in that location at the time of the Cycle 3 site visit.

The reader may also notice some of the feature photographs are used more than once. The practice of the same photograph being used for more than one feature was allowed during this cycle's data collection.

North Attleboro NFH

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface	Excellent		Good		Total	
Туре	Miles	%	Miles	%	Miles	
Native	0.41	55%	0.33	45%	0.74	
Total	0.41	55%	0.33	45%	0.74	

Trail Miles and Percentages by Trail Classification and Condition

Trail	Excellent		Good		Total	
Classification	Miles	%	Miles	%	Miles	
TC2	0.41	55%	0.33	45%	0.74	
Total	0.41	55%	0.33	45%	0.74	

^{*}Admin Roads are included in the inventory but are not rated for condition.


Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T200	Trailhead	1	No	0.00	NOAT_C3_000 5
T200	Sign	1	No	0.00	NOAT_C3_000 4
T200	Puncheon -If	25	No	0.03	NOAT_C3_000 7
T200	Max Grade- %	24	No	0.12	
T200	Sign	1	No	0.17	NOAT_C3_000 9
T200	Step: Log -each	39	No	0.18	
T200	Begin Section	1	No	0.33	NOAT_C3_001 2
T200	Sign	1	No	0.33	NOAT_C3_001
T200	Bench	1	No	0.34	
T200	Bridge -sf	126	No	0.34	NOAT_C3_001 3
T200	Begin Section	1	No	0.41	NOAT_C3_001 5
T200	Step: Log -each	29	No	0.43	
T200	Crib: Log -cf	44	No	0.63	
T200	Sign	1	No	0.70	NOAT_C3_001 9
T200	Sign	1	No	0.72	NOAT_C3_002 0
T200	Bridge -sf	198	No	0.73	NOAT_C3_002 1
T200	Sign	1	No	0.73	NOAT_C3_000 2
T200	Gate	1	No	0.73	

sf - square feet If - linear feet

cf - cubic feet

North Attleboro NFH Trail Location Map



Trails ID

Station Name: North Attleboro NFH Org Code: 53270

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T200	Nature Trail	Native	10023341	0.74	From North of Hatchery Office to End of loop

CHANGES TO THE FISH AND WILDLIFE SERVICE TRAIL INVENTORY REPORT

North Attleboro NFH

Trails added to previous inventory:					
Trail #	Trail Name	Reason for Addition			
		Trails removed from previous inventory:			
Trail #	Trail Name	Reason for Removal			
		Trails modified from previous inventory:			
Trail #	Trail Name	Type of Modification	Description of Modification		
Commen	ts:				

TRAIL CONDITION





Trail Name: Nature Trail Refuge Name: North Attleboro NFH **Trail Number:** T200 Region: 5

Section Number 001 002 003 Section Length (miles) 0.33 0.08 0.33 10023341 10023341 10023341 SAMMS Number 07/28/2006 07/28/2006 07/28/2006 Rating Date Trail Section Information TC2 TC2 TC2 Trail Class Native Native Native Surface Type Surface Firmness Firm Firm Firm Width (inches) 24 44 24 Average Grade (%) 5.4 5.4 5.4 Average X-slope (%) 1.70 1.70 1.70 **Trail Condition Information** \$593 \$0 **Deferred Maintenance** \$16,699 \$7,422 **CRV** \$16,699 0.02 0.00 0.00 FCI

Good

Trail Condition TOTALS

Excellent

Excellent

Deferred Maintenance	CRV	FCI	Condition
\$593	\$40,820	0.00	Excellent


Condition

Total Length: 0.74 Miles

NOTE TO USERS OR READERS

This section shows an updated condition assessment for each trail documented in this report. However there may be dates on the condition assessment pages that range from 2006 and 2007 to 2012. This occurred because the GPS dates of the trails originally rated in Cycle 1 were not updated when the Cycle 3 assessment was done to in 2012. That GPS date is the basis for the Rating date in the report. Any new trail or section of trail that was collected and rated in Cycle 3 will have a rating date of 2012. While the rating dates may show a pre 2012 date, each trail was walked and its condition was assessed in 2012 during the Cycle 3 field season.

TRAIL DEFICIENCY



TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0004 - MP 0.00 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0005 - MP 0.00 - Trailhead

TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0007 - MP 0.03 - Puncheon -If

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0009 - MP 0.17 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0011 - MP 0.33 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0012 - MP 0.33 - Begin Section

TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0013 - MP 0.34 - Bridge -sf

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0015 - MP 0.41 - Begin Section

TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0019 - MP 0.70 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0020 - MP 0.72 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH

DATE: 07/28/2006



Photo # NOAT_C3_0002 - MP 0.73 - Sign

TRAIL NUMBER: T200 STATION: North Attleboro NFH



Photo # NOAT_C3_0021 - MP 0.73 - Bridge -sf

A NOTE TO USERS OR READERS

In this chapter the reader may notice photographs with dates ranging from 2006 and 2007 to 2012. This occurs because existing photographs from cycle 1 were used if no significant or noticeable changes were seen in that location at the time of the cycle 3 site visit.

The reader may also notice some photographs are used more than once. The practice of the same photograph being used for more than one feature was allowed during this cycle's data collection.

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS SAMMS number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI > - .20 = Failed

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

i

Elem ID Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped features include non-unique signs (mileposts, **Grouped Features**

> interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity"

field of the data dictionary.

Type of accessibility information available at trailhead: Info Type

brochure, sign or other.

Item on which the "Action" (see above) will be **Item**

performed.

Managed use of the trail: HIKE, BIKE, NSPC (non-Manage Use

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

Distance of a trail feature or deficiency from the MP

Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail

Structure

Boardwalk, Turnpike, Puncheon.

Trail Class: I-V (see Appendix? for trail class T Class

descriptions).

Trail Designation: Standard (Std), National Historic Trail Tr Desig

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Trail tread elevated with dirt, rock or other aggregate Turnpike

from parallel side ditches and held in place by logs.