The Trail Inventory of Sevilleta National Wildlife Refuge Socorro, New Mexico





Prepared By: Federal Highway Administration Central Federal Lands Highway Division March 2006



Sevilleta NWR Trail and Trail Feature Summaries

	Mileage by Trail Condition									Total			
Trail Surface	Exce	ellent	Good		Fair		Poor		Very Poor		Not Rated*		Miles
Туре	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	Nines
Native	1.15	77%		0%		0%		0%		0%		0%	1.15
Gravel	0.06	4%		0%		0%		0%		0%		0%	0.06
Asphalt		0%		0%		0%		0%		0%		0%	0.00
Concrete	0.29	19%		0%		0%		0%		0%		0%	0.29
Turnpike		0%		0%		0%		0%		0%		0%	0.00
Boardwalk		0%		0%		0%		0%		0%		0%	0.00
Puncheon		0%		0%		0%		0%		0%		0%	0.00
Woodchips		0%		0%		0%		0%		0%		0%	0.00
Admin Road		0%		0%		0%		0%		0%		0%	0.00
Other		0%		0%		0%		0%		0%		0%	0.00
Totals	1.50	100%	0.00	0%	0.00	0%	0.00	0%	0.00	0%	0.00	0%	1.50

Trail Miles and Percentages by Surface Type and Condition

Trail Miles and Percentages by Trail Classification and Condition

		Mileage by Trail Condition									Total		
Trail	Exce	ellent	Go	od	Fair		Poor		Very Poor		Not Rated*		Miles
Classification	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	WIIC3
TC1		0%		0%		0%		0%		0%		0%	0.00
TC2		0%		0%		0%		0%		0%		0%	0.00
TC3	1.15	77%		0%		0%		0%		0%		0%	1.15
TC4	0.06	4%		0%		0%		0%		0%		0%	0.06
TC5	0.29	19%		0%		0%		0%		0%		0%	0.29
Totals	1.50	100%	0.00	0%	0.00	0%	0.00	0%	0.00	0%	0.00	0%	1.50


* Admin Roads are included in the inventory but are not rated for condition.

Trail Features	,
-----------------------	---

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
Т300	Bridge -sf	24	No	0.02	0278
T300	Sign	1	No	0.07	0280
T300	Bench	1	No	0.08	N/A
T300	Sign	1	No	0.08	0281
T300	Sign	1	No	0.10	N/A
T300	Sign	1	No	0.17	N/A
Т300	Bench	2	No	0.30	N/A
Т300	Sign	1	No	0.31	N/A
Т300	Sign	1	No	0.38	N/A
Т300	Sign	1	No	0.47	N/A
Т300	Bench	1	No	0.49	N/A
T300	Sign	1	No	0.50	N/A
T300	Sign	1	No	0.52	N/A
Т300	Bench	1	No	0.73	N/A
T300	Sign	1	No	0.96	N/A
T300	Bench	1	No	1.05	N/A
T500	Bench	1	No	0.15	N/A
T500	Bridge -sf	100	No	0.16	0276
T500	Bench	1	No	0.18	N/A
sf-square feet					

If-linear feet cf-cubic feet

SEVILLETA NATIONAL WILDLIFE REFUGE TRAIL LOCATION MAP





TRAILS ID

Station Name: Sevilleta NWR

Org. Code: 22522

Trail #	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Chihuahuan Desert Loop Trail	Native	10035830	1.21	Visitor Center entrance to End of Loop
T500	Accessibility Trail	Concrete	10035829	0.29	Backside of Visitor Center to Visitor Center entrance

TRAIL CONDITION

MP:0.02 (Br	MP:0.07 Bench) %, Sign) MP:0.17	Rte# 01	Parking Area) 0 (Refuge Head Begin Section MP:1.05 CMP 0.9	Iquarter's Roa	JAN SWAR	LEW BUNKER				
Excellent	1 inch equals 800 feet Excellent Good Fair Poor Very Poor Admin Road									
▲ Begin Section ↓ Trailhead ↓ Trail Sign ↓ Drainage Structure	Check Dam Retaining Wa Raised Trail S Water Bar		 Step Feature Max. Grade Min. Width Intersection 	_	dge ^W T	on Boundary				
Trail Name: Chihuahuan Dese Trail Number: T300	rt Loop Trail	-	e Name: Seville Region: 2	eta NWR	TOTAL LENG	GTH: 1.21 Miles				
Section Number Section Length (miles) SAMMS Number Rating Date		001 0.06 10035830 3/27/2006	002 1.15 10035830 3/27/2006							
Trail Section Information Trail Class Surface Type Surface Firmness Width (inches) Average Grade (%) Average X-slope (%)	n	TC4 Gravel Soft 36 4.8 3.4	TC3 Native Soft 50 4.8 3.4							
Trail Condition Informat Deferred Maintenance CRV FCI Condition	tion	\$0 \$6,100 0 Excellent	\$0 \$111,900 0 Excellent							
	Tr		ion TOTALS	<u> </u>	I					
Deferred										

Deferred Maintenance	CRV	FCI	Condition	
\$0	\$0 \$118,000		Excellent	

TRAIL CONDITION

Rte#900 (Visitor	's Ce	MP:0.		2:0	MP:0.14		Refu	ge He	eadquarte	er's Road)
1 inch equals 250 feet Excellent Good Fair Poor Very Poor Admin Road										
Excellent Excellent	Go	OD Check Dam	Fair 🧲		Poor Step Feature		200r ⊠ Gat		y Admin I	N N
Trailhead	2	Retaining Wa	all		Max. Grade	>	S Ga		w	Ю е
Trail Sign		Raised Trail S	Structure	ب ہ -	Min. Width	7	Ber			s
Drainage Structure		Water Bar		+	Intersection)	⊲ Oth	er	Statio	on Boundary
Trail Name: Accessibility Trai	I		Refu	-	Name: Seville	eta NWF	२			
Trail Number: T500				R	legion: 2	1		тот	AL LENG	TH: 0.29 Miles
Section Number			001		002					
Section Length (miles) SAMMS Number			0.15 10035829		0.14 10035829					
Rating Date			3/27/2006		3/27/2006					
Trail Section Informati	on									
Trail Class			TC5		TC5					
Surface Type Surface Firmness			Concrete Paved		Concrete Paved					
Width (inches)			60		60					
Average Grade (%)			2.5		2.5					
Average X-slope (%)			2.4		2.4					
Trail Condition Informa	ation	1								
Deferred Maintenance			\$0 \$07,400		\$0 \$21.500					
CRV FCI			\$27,400 0		\$31,500 0					
Condition			Excellent		Excellent					
Trail Condition TOTALS Deferred										

Deferred Maintenance	CRV	FCI	Condition
\$0	\$58,900	0	Excellent

TRAIL NUMBER: **T300** STATION: Sevilleta NWR DATE: 3/27/06



Photo #0277 - MP 0 - Trailhead

TRAIL NUMBER: **T300** STATION: Sevilleta NWR DATE: 3/27/05



TRAIL NUMBER: **T300** STATION: Sevilleta NWR DATE: 3/27/06



Photo #0279 - MP .06 - Begin Section 002

TRAIL NUMBER: **T300** STATION: Sevilleta DATE: 3/27/05



Photo #0280 - MP .07 - Sign

TRAIL NUMBER: **T300** STATION: Sevilleta NWR DATE: 3/27/06



Photo #0281 - MP .07 - Sign

TRAIL NUMBER: **T500** STATION: Sevilleta NWR DATE: 3/27/05



Photo #0274 - MP 0 - Trailhead

TRAIL NUMBER: **T500** STATION: Sevilleta NWR DATE: 3/27/06



Photo #0275 - MP .14 - Begin Section 002

TRAIL NUMBER: **T500** STATION: Sevilleta NWR DATE: 3/27/05

