
The Trail Inventory of U.S. Fish and Wildlife Service Stations In INDIANA



Prepared By: Federal Highway Administration Central Federal Lands Highway Division October 2006





TABLE OF CONTENTS

<u>CHAPTER</u>		PAGE
1.	IN STATE SUMMARY Table of Contents	1-1
	List of Refuges Mileage by Trail Class, Condition, and Surface	1-2 1-3
2-3.	REFUGE SUMMARIES	
	Mileage by Trail Class, Condition, and Surface	X-1
	Trail Location Map	X-2
	Trail Identification	X-3
	Condition and Deficiency Sheets	X-4
	Photographic Sheets	X-5
4.	<u>APPENDIX</u>	
	Glossary of Terms and Abbreviations	4-1
	Trail Classification System	4-4

FWS Stations in Indiana with Trails

Station Name	Trail Miles	Chapter
Muscatatuck NWR	9.95	2
Patoka River NWR	1.07	3

Indiana FWS Stations Trail Summaries

Trail Miles and Percentages by Surface Type and Condition

					Milea	age by T	rail Cond	dition					Total
Trail Surface	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	Rated*	Miles
Туре	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
Native	0.63	6%	0.14	1%	3.50	32%		0%	1.31	12%		0%	5.58
Gravel	0.71	6%		0%		0%		0%		0%		0%	0.71
Asphalt	0.10	1%		0%		0%		0%		0%		0%	0.10
Concrete	0.07	1%		0%		0%		0%		0%		0%	0.07
Turnpike		0%		0%		0%		0%		0%		0%	0.00
Boardwalk	0.36	3%		0%		0%		0%		0%		0%	0.36
Puncheon		0%		0%		0%		0%		0%		0%	0.00
Woodchips		0%		0%		0%		0%		0%		0%	0.00
Mowed	1.38	13%	1.50	14%	0.40	4%	0.22	2%	0.70	6%		0%	4.20
Admin Road		0%		0%		0%		0%		0%		0%	0.00
Other		0%		0%		0%		0%		0%		0%	0.00
Totals	3.25	29%	1.64	15%	3.90	35%	0.22	2%	2.01	18%	0.00	0%	11.02

Trail Miles and Percentages by Trail Classification and Condition

Trail		Mileage by Trail Condition										Total	
Classificatio	Exce	ellent	Go	od	Fa	Fair Poo		oor Very Poor		Not Rated*		Miles	
n	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
TC1		0%		0%		0%		0%		0%		0%	0.00
TC2	0.02	0%		0%		0%		0%		0%		0%	0.02
TC3	2.70	25%	1.64	15%	3.90	35%	0.22	2%	2.01	18%		0%	10.47
TC4	0.06	1%		0%		0%		0%		0%		0%	0.06
TC5	0.47	4%		0%		0%		0%		0%		0%	0.47
Totals	3.25	29%	1.64	15%	3.90	35%	0.22	2%	2.01	18%	0.00	0%	11.02

^{*} Admin Roads are included in the inventory but are not rated for condition.

The Trail Inventory of Muscatatuck National Wildlife Refuge Seymour, Indiana





Prepared By: Federal Highway Administration Central Federal Lands Highway Division October 2006



Muscatatuck NWR Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

					Milea	age by T	rail Cond	dition					Total
Trail Surface	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	Rated*	Miles
Туре	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
Native	0.41	4%	0.14	1%	3.50	35%		0%	1.31	13%		0%	5.36
Gravel	0.51	5%		0%		0%		0%		0%		0%	0.51
Asphalt	0.10	1%		0%		0%		0%		0%		0%	0.10
Concrete	0.07	1%		0%		0%		0%		0%		0%	0.07
Turnpike		0%		0%		0%		0%		0%		0%	0.00
Boardwalk	0.33	3%		0%		0%		0%		0%		0%	0.33
Puncheon		0%		0%		0%		0%		0%		0%	0.00
Woodchips		0%		0%		0%		0%		0%		0%	0.00
Mowed	1.16	12%	1.50	15%		0%	0.22	2%	0.70	7%		0%	3.58
Admin Road		0%		0%		0%		0%		0%		0%	0.00
Other		0%	·	0%		0%		0%		0%		0%	0.00
Totals	2.58	26%	1.64	16%	3.50	35%	0.22	2%	2.01	20%	0.00	0%	9.95

Trail Miles and Percentages by Trail Classification and Condition

Trail		Mileage by Trail Condition										Total	
Classificatio	Exce	ellent	Go	od	Fa	air	Po	or	Very Poor		Not Rated*		Miles
n	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
TC1		0%		0%		0%		0%		0%		0%	0.00
TC2		0%		0%		0%		0%		0%		0%	0.00
TC3	2.08	21%	1.64	16%	3.50	35%	0.22	2%	2.01	20%		0%	9.45
TC4	0.06	1%		0%		0%		0%		0%		0%	0.06
TC5	0.44	4%		0%		0%		0%		0%		0%	0.44
Totals	2.58	26%	1.64	16%	3.50	35%	0.22	2%	2.01	20%	0.00	0%	9.95

^{*} Admin Roads are included in the inventory but are not rated for condition.


Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T300	Sign	1	No	0.00	1003
T300	Lookout/Ob Deck	1	No	0.36	N/A
T300	Culvert -If	20	No	0.38	N/A
T300	Sign	2	No	0.46	1005
T300	Culvert -If	15	No	0.67	N/A
T300	Culvert -If	20	No	0.73	N/A
T301	Sign	1	No	0.00	1013
T301	Sign	3	No	0.09	1015
T301	Sign	2	No	0.22	1019
T301	Culvert -If	10	No	0.59	N/A
T302	Sign	1	No	0.00	1025
T302	Sign	10	Yes	0.05	1026
T302	Culvert -If	15	No	0.05	N/A
T302	Bridge -sf	200	No	0.31	1033
T302	Bridge -sf	75	No	0.32	1034
T302	Bridge -sf	60	No	0.34	1036
T302	Culvert -If	50	No	0.00	N/A
T303	Sign	1	No	0.00	1042
T303	Gate	1	No	0.00	N/A
T303	Sign	2	No	0.42	1045
T303	Bridge -sf	150	No	0.54	1046
T303	Sign	1	No	1.50	1050
T303	Bench	1	No	1.50	N/A
T303	Other	1	No	1.63	1052
T303	Sign	2	No	1.75	1055
T303	Sign	2	No	2.05	1058
T303	Culvert -If	20	No	2.30	N/A
T304	Sign	1	No	0.86	1881
T304	Culvert -If	15	No	0.85	N/A
T304	Culvert -If	30	No	0.99	N/A
T305	Bridge -sf	100	No	0.05	1068
T305	Sign	1	No	0.06	1069
T305	Sign	2	No	0.10	1072
T305	Step: Log -each	17	Yes	0.11	N/A
T305	Bench	2	No	0.14	N/A
T305	Other	1	No	0.14	1075
T305	Sign	1	No	0.14	1075
T306	Sign	4	No	0.00	1077
T306	Sign	4	No	0.31	1086
T307	Sign	1	No	0.00	1091
T307	Culvert -If	25	No	0.14	N/A
T308	Sign	1	No	0.00	1883
T308	Sign Bridge of	2	No	0.96	1885-6
T308 T308	Bridge -sf Sign	75 1	No No	0.15 0.26	1888 1891
T308	Sign	1	No	0.26	1891
T308	Sign	1	No	0.32	1893
T308	Culvert -If	6	No	0.42	N/A
T308	Sign	3	No	0.50	1896
T308	Sign	2	No	0.50	1897
T308	Bridge -sf	60	No	0.53	1903

T308	Sign	2	No	0.83	1908
T308	Sign	2	No	0.84	1909
T308	Culvert -If	25	No	0.91	N/A
T309	Sign	1	No	0.00	1909
T309	Sign	1	No	0.00	1910
T309	Sign	1	No	0.08	1915
T500	Sign	1	No	0.00	0997
T500	Sign	13	Yes	0.02	0998
T500	Culvert -If	15	No	0.05	N/A
T500	Bench	1	No	0.08	N/A
T500	Step: Log -each	20	No	0.07	N/A
T500	Culvert -If	15	No	0.16	N/A
T500	Culvert -If	15	No	0.17	N/A
T500	Bench	1	No	0.29	N/A
T500	Culvert -If	15	No	0.31	N/A
T500	Culvert -If	16	No	0.33	N/A
T500	Bench	1	No	0.36	N/A
T501	Sign	4	No	0.00	1087

sf-square feet If-linear feet cf-cubic feet


MUSCATATUCK NATIONAL WILDLIFE REFUGE TRAIL LOCATION MAP



TRAILS ID

Station Name: Muscatatuck NWR Org. Code: 31530

Trail #	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Richart Trail	Mowed, Native	10054481	0.88	From Hackman Overlook Parking (Rte 920) to end of trail loop
T301	Bird Trail	Native	N/A	0.71	From Bird Trail Parking (Rte 921) to end of trail loop
T302	Wood Duck Trail	Gravel	N/A	0.49	From Storm Creek Parking (Rte 913) to end of trail loop
T303	River Trail - East	Mowed, Native	10054487	2.31	From Myers Cabin/Lake Linda Road (Rte 104) to Sec 001
T304	River Trail - West	Native	10054487	3	From River Trail - East (T303) North intersection to River Trail - East (T303) South intersection
T305	Myer's Cabin Trail	Native	10054487	0.14	From Myers Cabin South roadside Parking (Rte 910) to end of trail
T306	Persimmon Ponds Trail	Mowed	10054486	0.36	From Persimmon Pond Parking A (Rte 907) to Myers Cabin/Lake Linda Road (Rte 104)
T307	Mallard Pond Trail	Mowed	10054482	0.22	From Mallard Pond Parking (Rte 916) to County Line Road (Rte 010)
T308	Turkey Trail	Native	N/A	0.96	From Turkey Trail Parking (Rte 912) to end of trail loop
T309	Endicott Trail	Mowed, Native	10054484	0.3	From Endicott Trail Parking (Rte 919) to end of trail loop
T500	Chestnut Ridge Trail	Asphalt, Gravel, Boardwalk	10010623	0.45	From Visitor Center Parking A (Rte 901) to Visitor's Center
T501	Sandhill Ponds Trail	Concrete, Mowed	10049634	0.13	From Sandhill Ponds Parking (Rte 925) to end of trail




Trail Name: Richart Trail Refuge Name: Muscatatuck NWR

Trail Number: T300 Region: 3 TOTAL LENGTH: 0.88 Miles


		_		IOINE EEITO	, i i i. 0.00 ivilio
Section Number	001	002	003		
Section Length (miles)	0.61	0.14	0.13		
SAMMS Number	10054481	10054481	10054481		
Rating Date	10/20/2006	10/20/2006	10/20/2006		
Trail Section Information					
Trail Class	TC3	TC3	TC3		
Surface Type	Mowed	Native	Mowed		
Surface Firmness	Firm	Firm	Firm		
Width (inches)	105	72	105		
Average Grade (%)	1.3	1.3	1.3		
Average X-slope (%)	1.4	1.4	1.4		
Trail Condition Information					
Deferred Maintenance	\$0	\$8800	\$0		
CRV	\$32500	\$22500	\$6300		
FCI	0	0.391	0		
Condition	Excellent	Very Poor	Excellent		

Deferred Maintenance	CRV	FCI	Condition
\$8800	\$61300	0.144	Poor




Trail Name: Richart Trail Refuge Name: Muscatatuck NWR

Mile Post	0.64	0.64	0.74	0.74
Section Number	002	002	002	002
Photo Number	1007	1007	1009	1009
Deficiency	Erosion	Erosion	Erosion	Erosion
Action	Build/Add	Repair	Repair	Build/Add
Item	Water Bar:Wood -each	Tread -sf	Tread -sf	Drainage Ditch -If
Quantity	3	300	100	25
Deferred Maintenance	\$300	\$700	\$300	\$100



Trail Name: Richart Trail Refuge Name: Muscatatuck NWR


Section Number Photo Number Deficiency Action Item Quantity Deferred Maintenance 002 1009 Erosion Build/Add Berosion Build/Add Build/Add Turnpike -If 2 150 \$7100	Mile Post	0.74	0.65	
Deficiency Action Item Quantity Erosion Build/Add Build/Add Water Bar:Wood -each Quantity Drainage Build/Add Turnpike -If 2 150	Section Number	002	002	
Action Build/Add Build/Add Item Water Bar:Wood -each Quantity 2 150	Photo Number	1009	1008	
Item Quantity Water Bar:Wood -each 2 Turnpike -If 2 150	Deficiency	Erosion	Drainage	
Quantity 2 150	Action	Build/Add	Build/Add	
	Item	Water Bar:Wood -each	Turnpike -If	
Deferred Maintenance \$200 \$7100	Quantity	2	150	
	Deferred Maintenance	\$200	\$7100	



Trail Name: Bird Trail Refuge Name: Muscatatuck NWR


Trail Number: T301		Region: 3	T	OTAL LENG	TH: 0.71 Miles
Section Number	001				
Section Length (miles)	0.71				
SAMMS Number	N/A				
Rating Date	10/20/2006				
Trail Section Information					
Trail Class	TC3				
Surface Type	Native				
Surface Firmness	Firm				
Width (inches)	40				
Average Grade (%)	2.6				
Average X-slope (%)	1.9				
Trail Condition Information					
Deferred Maintenance	\$14900				
CRV	\$54800				
FCI	0.272				
Condition	Very Poor				

Deferred Maintenance	CRV	FCI	Condition
\$14900	\$54800	0.272	Very Poor




Trail Name: Bird Trail Refuge Name: Muscatatuck NWR

			. •	
Mile Post	0.62	0.62	0.03	0.11
Section Number	001	001	001	001
Photo Number	1024	1024	1014	1016
Deficiency	Erosion	Erosion	Drainage	Drainage
Action	Build/Add	Repair	Build/Add	Build/Add
Item	Water Bar:Wood -each	Tread -sf	Turnpike -If	Turnpike -If
Quantity	2	75	30	75
Deferred Maintenance	\$200	\$200	\$1500	\$3600



Trail Name: Bird Trail Refuge Name: Muscatatuck NWR

Mile Post	0.13	0.22	0.23	0.26
Section Number	001	001	001	001
Photo Number	1017	1018	1020	1022
Deficiency	Drainage	Drainage	Drainage	Drainage
Action	Build/Add	Build/Add	Build/Add	Build/Add
Item	Turnpike -If	Turnpike -If	Turnpike -If	Boardwalk -If
Quantity	100	50	15	40
Deferred Maintenance	\$4800	\$2400	\$800	\$1500



Trail Name: Wood Duck Trail Refuge Name: Muscatatuck NWR

Trail Number: T302 Region: 3 TOTAL LENGTH: 0.49 Miles Section Number 001 Section Length (miles) 0.49 SAMMS Number N/A 10/20/2006 Rating Date

TC3

Gravel

Firm

48

4.4

1.4


Trail Section Information Trail Class

Surface Type Surface Firmness Width (inches) Average Grade (%) Average X-slope (%)

Trail Condition Information

Deferred Maintenance \$0 **CRV** \$74300 **FCI** 0 Condition Excellent

Deferred Maintenance	CRV	FCI	Condition
\$0	\$74300	0	Excellent




Trail Name: River Trail - East Refuge Name: Muscatatuck NWR

Trail Number: T303 Region: 3 TOTAL LENGTH: 2.31 Miles


				TOTAL LENG	
Section Number	001	002	003	004	
Section Length (miles)	1.5	0.19	0.35	0.27	
SAMMS Number	10054487	10054487	10054487	10054487	
Rating Date	10/21/2006	10/21/2006	10/21/2006	10/21/2006	
Trail Section Information					
Trail Class	TC3	TC3	TC3	TC3	
Surface Type	Mowed	Native	Mowed	Mowed	
Surface Firmness	Firm	Firm	Firm	Firm	
Width (inches)	108	84	84	108	
Average Grade (%)	2.5	2.5	2.5	2.5	
Average X-slope (%)	1.5	1.5	1.5	1.5	
Trail Condition Information					
Deferred Maintenance	\$4100	\$0	\$7000	\$5300	
CRV	\$86700	\$30700	\$14100	\$15700	
FCI	0.047	0	0.496	0.338	
Condition	Good	Excellent	Very Poor	Very Poor	

Deferred Maintenance	CRV	FCI	Condition
\$16400	\$147200	0.111	Poor




Trail Name: River Trail - East Refuge Name: Muscatatuck NWR

Mile Post	1.16	0.73	0.73	1.11
Section Number	001	001	001	001
Photo Number	1049	1047	1047	1048
Deficiency	Trail Structure	Drainage	Drainage	Drainage
Action	Replace	Build/Add	Build/Add	Build/Add
Item	Culvert -If	Drainage Ditch -If	Tread -sf	Culvert -If
Quantity	15	2	50	20
Deferred Maintenance	\$1900	\$100	\$100	\$2000




Trail Name: River Trail - East Refuge Name: Muscatatuck NWR

Mile Post	0.15	1.72	1.73	1.83
Section Number	001	003	003	003
Photo Number	1065	1054	1054	1056
Deficiency	Drainage	Erosion	Erosion	Drainage
Action	Build/Add	Build/Add	Repair	Build/Add
Item	Culvert -If	Culvert -If	Tread -sf	Bridge -sf
Quantity	30	20	150	75
Deferred Maintenance	\$3000	\$2000	\$100	\$4200



Trail Name: River Trail - East Refuge Name: Muscatatuck NWR


Mile Post	2.02	2.06	2.07	2.1
Section Number	003	004	004	004
Photo Number	1057	1060	1061	1062
Deficiency	Drainage	Drainage	Drainage	Drainage
Action	Build/Add	Build/Add	Build/Add	Build/Add
Item	Drainage Ditch -If	Drainage Ditch -If	Drainage Dips -each	Drainage Dips -each
Quantity	150	200	2	3
Deferred Maintenance	\$600	\$900	\$200	\$200
		1		



Trail Name: River Trail - East Refuge Name: Muscatatuck NWR

Mile Post	2.1	2.17	2.17
Section Number	004	004	004
Photo Number	1062	1063	1063
Deficiency	Drainage	Drainage	Drainage
Action	Build/Add	Build/Add	Build/Add
Item	Drainage Ditch -If	Drainage Ditch -If	Drainage Dips -each
Quantity	100	100	2
Deferred Maintenance	\$400	\$400	\$200

Condition



Trail Name: River Trail - West Refuge Name: Muscatatuck NWR

Trail Number: T304 Region: 3 TOTAL LENGTH: 3 Miles


Section Number 001 Section Length (miles) 3

Occion Namber	001		
Section Length (miles)	3		
SAMMS Number	10054487		
Rating Date	10/21/2006		
Trail Section Information			
Trail Class	TC3		
Surface Type	Native		
Surface Firmness	Firm		
Width (inches)	84		
Average Grade (%)	2.5		
Average X-slope (%)	1.5		
Trail Condition Information			
Deferred Maintenance	\$29400		
CRV	\$482700		
FCI	0.061		

Trail Condition TOTALS


Fair

Deferred Maintenance	CRV	FCI	Condition
\$29400	\$482700	0.061	Fair



Trail Name: River Trail - West Refuge Name: Muscatatuck NWR

			_
Mile Post	0.04	0.88	
Section Number	001	001	
Photo Number	1880	1882	
Deficiency	Drainage	Drainage	
Action	Build/Add	Build/Add	
Item	Drainage Ditch -If	Bridge -sf	
Quantity	350	500	
Deferred Maintenance	\$1500	\$28000	




Trail Name: Myer's Cabin Trail Refuge Name: Muscatatuck NWR

Trail Number: T305 Region: 3 TOTAL LENGTH: 0.14 Miles


		101/12 EE110	TITLE OF IT A INTINCO
Section Number	001		
Section Length (miles)	0.14		
SAMMS Number	10054487		
Rating Date	10/21/2006		
Trail Section Information			
Trail Class	TC3		
Surface Type	Native		
Surface Firmness	Firm		
Width (inches)	36		
Average Grade (%)	7.2		
Average X-slope (%)	0.8		
Trail Condition Information			
Deferred Maintenance	\$200		
CRV	\$17000		
FCI	0.012		
Condition	Good		

Deferred Maintenance	CRV	FCI	Condition
\$200	\$17000	0.012	Good



Trail Name: Myer's Cabin Trail Refuge Name: Muscatatuck NWR

0.04	0.04
001	001
1067	1067
Erosion	Erosion
Repair	Build/Add
Tread -sf	Water Bar:Wood -each
15	1
\$100	\$100
	001 1067 Erosion Repair Tread -sf 15




Trail Name: Persimmon Ponds Trail Refuge Name: Muscatatuck NWR

Trail Number: T306 Region: 3 TOTAL LENGTH: 0.36 Miles

		<u> </u>		TOTAL LLING	TITI. U.SU IVIIIES
Section Number	001	002	003		
Section Length (miles)	0.13	0.03	0.2		
SAMMS Number	10054486	10054486	10054486		
Rating Date	10/21/2006	10/21/2006	10/21/2006		
Trail Section Information					
Trail Class	TC3	TC3	TC3		
Surface Type	Mowed	Mowed	Mowed		
Surface Firmness	Firm	Firm	Firm		
Width (inches)	180	180	180		
Average Grade (%)	1.7	1.7	1.7		
Average X-slope (%)	2.3	2.3	2.3		
Trail Condition Information					
Deferred Maintenance	\$0	\$0	\$0		
CRV	\$10700	\$2200	\$16900		
FCI	0	0	0		
Condition	Excellent	Excellent	Excellent		

Deferred Maintenance	CRV	FCI	Condition
\$0	\$29800	0	Excellent



Trail Name: Mallard Pond Trail Refuge Name: Muscatatuck NWR

Trail Number: T307 Region: 3 TOTAL LENGTH: 0.22 Miles Section Number 001 Section Length (miles) 0.22 SAMMS Number 10054482 Rating Date 10/21/2006

TC3

Mowed

Firm

120

4.6

2.4


Trail Section Information Trail Class Surface Type

Surface Firmness Width (inches) Average Grade (%) Average X-slope (%)

Trail Condition Information


Deferred Maintenance \$2600 **CRV** \$14800 **FCI** 0.176 Condition Poor

Deferred Maintenance	CRV	FCI	Condition
\$2600	\$14800	0.176	Poor




Trail Name: Mallard Pond Trail Refuge Name: Muscatatuck NWR

Mile Post	0.02	0.04	0.08	0.09
Section Number	001	001	001	001
Photo Number	1093	1094	1095	1095
Deficiency	Drainage	Drainage	Drainage	Drainage
Action	Repair	Repair	Build/Add	Build/Add
Item	Tread -sf	Tread -sf	Drainage Ditch -If	Drainage Dips -each
Quantity	100	125	75	4
Deferred Maintenance	\$100	\$100	\$300	\$300



Trail Name: Mallard Pond Trail Refuge Name: Muscatatuck NWR


Mile Post	0.18		
Section Number	001		
Photo Number	1099		
Deficiency	Drainage		
Action	Build/Add		
Item	Boardwalk -If		
Quantity	50		
Deferred Maintenance	\$1800		



Trail Name: Turkey Trail Refuge Name: Muscatatuck NWR


Trail Number: T308		Region: 3	TOTAL LENGTH: 0.96 Miles
Section Number	001	002	
Section Length (miles)	0.5	0.46	
SAMMS Number	N/A	N/A	
Rating Date	10/21/2006	10/21/2006	
Trail Section Information			
Trail Class	TC3	TC3	
Surface Type	Native	Native	
Surface Firmness	Firm	Firm	
Width (inches)	30	30	
Average Grade (%)	1.7	1.7	
Average X-slope (%)	2	2	
Trail Condition Information			
Deferred Maintenance	\$3200	\$27900	
CRV	\$33000	\$31900	
FCI	0.097	0.875	
Condition	Fair	Very Poor	

Deferred Maintenance	CRV	FCI	Condition	
\$31100	\$64900	0.479	Very Poor	




Trail Name: Turkey Trail Refuge Name: Muscatatuck NWR

				2221101111 0.00 1111100	
Mile Post	0.16	0.16	0.43	0.43	
Section Number	001	001 001	001	001	
Photo Number	1889	9 1889 1894		1894	
Deficiency	Erosion	Erosion	Erosion	Erosion	
Action	Build/Add	Repair	Repair	Build/Add	
Item	Water Bar:Wood -each	Tread -sf	Tread -sf	Water Bar:Wood -each	
Quantity	3	75	200	4	
Deferred Maintenance	\$300	\$200	\$500	\$400	
	1				



Trail Name: Turkey Trail Refuge Name: Muscatatuck NWR


Mile Post	0.45	0.52	0.53	0.54
Section Number	001	002	002	002
Photo Number	1895	1899	1902	1904
Deficiency	Drainage	Drainage	Drainage	Drainage
Action	Build/Add	Build/Add	Build/Add	Build/Add
Item	Boardwalk -If	Boardwalk -If	Bridge -sf	Turnpike -If
Quantity	50	25	75	125
Deferred Maintenance	\$1800	\$900	\$4200	\$6000
	1			



Trail Name: Turkey Trail Refuge Name: Muscatatuck NWR

			101712 221101111 0:00 1/111100
Mile Post	0.8	0.82	
Section Number	002	002	
Photo Number	1905	1906	
Deficiency	Drainage	Drainage	
Action	Build/Add	Build/Add	
Item	Bridge -sf	Bridge -sf	
Quantity	200	100	
Deferred Maintenance	\$11200	\$5600	
		1	

Condition



Trail Name: Endicott Trail Refuge Name: Muscatatuck NWR

 Trail Number: T309
 Region: 3
 TOTAL LENGTH: 0.3 Miles

 Section Number
 001
 002

 Section Length (miles)
 0.08
 0.22

 SAMMS Number
 10054484
 10054484

 Rating Date
 10/21/2006

 Trail Section Information
 TC3
 TC3


Rating Date	10/21/2006	10/21/2006	
Trail Section Information			
Trail Class	TC3	TC3	
Surface Type	Mowed	Native	
Surface Firmness	Firm	Firm	
Width (inches)	120	72	
Average Grade (%)	4.9	4.9	
Average X-slope (%)	3	3	
Trail Condition Information			
Deferred Maintenance	\$5500	\$0	
CRV	\$4500	\$30100	
FCI	1.222	0	

Trail Condition TOTALS

Excellent

Very Poor


Deferred Maintenance	CRV	FCI	Condition	
\$5500	\$34600	0.159	Poor	



Trail Name: Endicott Trail Refuge Name: Muscatatuck NWR

Mile Post	0.01	0.03	0.23	0.25
Section Number	001	001	002	002
Photo Number	1913	1914	1918	1919
Deficiency	Erosion	Drainage	Drainage	Drainage
Action	Repair	Build/Add	Build/Add	Build/Add
Item	Tread -sf	Boardwalk -If	Boardwalk -If	Boardwalk -If
Quantity	100	50	25	75
Deferred Maintenance	\$100	\$1800	\$900	\$2700
	I	1	I	

TRAIL CONDITION



Trail Name: Chestnut Ridge Trail Refuge Name: Muscatatuck NWR


Trail Number: T500 Region: 3 TOTAL LENGTH: 0.45 Miles

		9		TOTAL LLING	TITLU.43 WIIIGS
Section Number	001	002	003	004	
Section Length (miles)	0.1	0.06	0.02	0.27	
SAMMS Number	10010623	10010623	10010623	10010623	
Rating Date	10/20/2006	10/20/2006	10/20/2006	10/20/2006	
Trail Section Information					
Trail Class	TC5	TC4	TC3	TC5	
Surface Type	Asphalt	Boardwalk	Gravel	Boardwalk	
Surface Firmness	Paved	Hard	Hard	Paved	
Width (inches)	100	72	75	100	
Average Grade (%)	4.2	4.2	4.2	4.2	
Average X-slope (%)	2.3	2.3	2.3	2.3	
Trail Condition Information					
Deferred Maintenance	\$0	\$0	\$0	\$0	
CRV	\$29400	\$48000	\$3000	\$281800	
FCI	0	0	0	0	
Condition	Excellent	Excellent	Excellent	Excellent	

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$0	\$362200	0	Excellent

TRAIL CONDITION



Trail Name: Sandhill Ponds Trail Refuge Name: Muscatatuck NWR

Trail Number: T501 Region: 3 TOTAL LENGTH: 0.13 Mile

Trail Hamber: 1501		ixegion. 3	TOTAL LENGTH: 0.13 Miles
Section Number	001	002	
Section Length (miles)	0.07	0.06	
SAMMS Number	10049634	10049634	
Rating Date	10/21/2006	10/21/2006	
Trail Section Information			
Trail Class	TC5	TC3	
Surface Type	Concrete	Mowed	
Surface Firmness	Paved	Firm	
Width (inches)	72	120	
Average Grade (%)	1.5	1.5	
Average X-slope (%)	2.3	2.3	
Trail Condition Information			
Deferred Maintenance	\$0	\$0	
CRV	\$14600	\$3600	
FCI	0	0	
Condition	Excellent	Excellent	

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$0	\$18200	0	Excellent

TRAIL NUMBER: **T300** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1004 - MP 0.0 - Trailhead

TRAIL NUMBER: **T300**

STATION: Muscatatuck NWR




Photo # 1003 - MP 0.0 - Sign

TRAIL NUMBER: **T300** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1005 - MP 0.46 - Sign

TRAIL NUMBER: **T300**

STATION: Muscatatuck NWR



Photo # 1006 - MP 0.61 - Begin Section 002

TRAIL NUMBER: **T300** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1007 - MP 0.64 - Erosion Deficiency

TRAIL NUMBER: **T300**

STATION: Muscatatuck NWR



Photo # 1008 - MP 0.65 - Drainage Deficiency

TRAIL NUMBER: **T300** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1009 - MP 0.74 - Erosion Deficiency

TRAIL NUMBER: **T300**

STATION: Muscatatuck NWR



Photo # 1011 - MP 0.75 - Begin Section 003

TRAIL NUMBER: **T301**

STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1012 - MP 0.0 - Trailhead

TRAIL NUMBER: T301

STATION: Muscatatuck NWR



Photo # 1013 - MP 0.0 - Sign

TRAIL NUMBER: **T301** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1014 - MP 0.03 - Drainage Deficiency

TRAIL NUMBER: **T301**

STATION: Muscatatuck NWR



Photo # 1015 - MP 0.09 - Sign

TRAIL NUMBER: **T301**

STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1016 - MP 0.11 - Drainage Deficiency

TRAIL NUMBER: T301

STATION: Muscatatuck NWR



Photo # 1017 - MP 0.13 - Drainage Deficiency

TRAIL NUMBER: **T301** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1018 - MP 0.22 - Drainage Deficiency

TRAIL NUMBER: **T301**

STATION: Muscatatuck NWR



Photo # 1019 - MP 0.22 - Sign

TRAIL NUMBER: **T301** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1020 - MP 0.23 - Drainage Deficiency

TRAIL NUMBER: **T301**

STATION: Muscatatuck NWR



Photo # 1022 - MP 0.26 - Drainage Deficiency

TRAIL NUMBER: **T301** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1024 - MP 0.62 - Erosion Deficiency

TRAIL NUMBER: **T302**

STATION: Muscatatuck NWR



Photo # 1025 - MP 0.0 - Trailhead, Sign

TRAIL NUMBER: **T302** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1026 - MP 0.05 - Sign (Grouped)

TRAIL NUMBER: **T302**

STATION: Muscatatuck NWR



Photo # 1033 - MP 0.31 - Bridge

TRAIL NUMBER: **T302** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1034 - MP 0.32 - Bridge

TRAIL NUMBER: **T302**

STATION: Muscatatuck NWR



Photo # 1036 - MP 0.34 - Bridge

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1043 - MP 0.0 - Trailhead

TRAIL NUMBER: T303

STATION: Muscatatuck NWR



Photo # 1042 - MP 0.0 - Sign

TRAIL NUMBER: **T303**STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1065 - MP 0.15 - Drainage Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1045 - MP 0.42 - Sign

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1046 - MP 0.54 - Bridge

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1047 - MP 0.73 - Drainage Deficiency

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1048 - MP 1.11 - Drainage Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1049 - MP 1.16 - Trail Structure Deficiency

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1050 - MP 1.5 - Sign

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1051 - MP 1.5 - Begin Section 002

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1052 - MP 1.63 - Other (cemetary)

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1053 - MP 1.7 - Begin Section 003

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1054 - MP 1.72 - Erosion Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1055 - MP 1.75 - Sign

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1056 - MP 1.83 - Drainage Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1057 - MP 2.02 - Drainage Deficiency

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1058 - MP 2.05 - Sign

TRAIL NUMBER: T303

STATION: Muscatatuck NWR



Photo # 1059 - MP 2.05 - Begin Section 004

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1060 - MP 2.06 - Drainage Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1061 - MP 2.07 - Drainage Deficiency

TRAIL NUMBER: **T303** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1062 - MP 2.1 - Drainage Deficiency

TRAIL NUMBER: **T303**

STATION: Muscatatuck NWR



Photo # 1063 - MP 2.17 - Drainage Deficiency

TRAIL NUMBER: **T304** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1879 - MP 0.0 - Trailhead

TRAIL NUMBER: **T304**

STATION: Muscatatuck NWR



Photo # 1880 - MP 0.04 - Drainage Deficiency

TRAIL NUMBER: **T304** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1881 - MP 0.86 - Sign

TRAIL NUMBER: T304

STATION: Muscatatuck NWR



Photo # 1882 - MP 0.88 - Drainage Deficiency

TRAIL NUMBER: **T305** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1066 - MP 0.0 - Trailhead

TRAIL NUMBER: **T305**

STATION: Muscatatuck NWR



Photo # 1067 - MP 0.04 - Erosion Deficiency

TRAIL NUMBER: **T305** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1068 - MP 0.05 - Bridge

TRAIL NUMBER: **T305**

STATION: Muscatatuck NWR



Photo # 1069 - MP 0.06 - Sign

TRAIL NUMBER: **T305** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1072 - MP 0.1 - Sign

TRAIL NUMBER: **T305**

STATION: Muscatatuck NWR




Photo # 1075 - MP 0.14 - Other (Myer's Cabin), Sign

TRAIL NUMBER: **T306** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1078 - MP 0.0 - Trailhead

TRAIL NUMBER: **T306**

STATION: Muscatatuck NWR



Photo # 1077 - MP 0.0 - Sign

TRAIL NUMBER: **T306** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1079 - MP 0.11 - Begin Section 003

TRAIL NUMBER: **T306**

STATION: Muscatatuck NWR



Photo # 1080 - MP 0.11 - Begin Section 002

TRAIL NUMBER: **T306** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1086 - MP 0.31 - Sign

TRAIL NUMBER: **T307**

STATION: Muscatatuck NWR



Photo # 1092 - MP 0.0 - Trailhead

TRAIL NUMBER: **T307** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1091 - MP 0.0 - Sign

TRAIL NUMBER: T307

STATION: Muscatatuck NWR



Photo # 1093 - MP 0.02 - Drainage Deficiency

TRAIL NUMBER: **T307** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1094 - MP 0.04 - Drainage Deficiency

TRAIL NUMBER: T307

STATION: Muscatatuck NWR



Photo # 1095 - MP 0.08 - Drainage Deficiency

TRAIL NUMBER: **T307** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1099 - MP 0.18 - Drainage Deficiency

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1884 - MP 0.0 - Trailhead

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1883 - MP 0.0 - Sign

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1888 - MP 0.15 - Bridge

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1889 - MP 0.16 - Erosion Deficiency

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1891 - MP 0.26 - Sign

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1892 - MP 0.32 - Sign

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1893 - MP 0.42 - Sign

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1894 - MP 0.43 - Erosion Deficiency

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1895 - MP 0.45 - Drainage Deficiency

TRAIL NUMBER: **T308**STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1896 - MP 0.5 - Sign

TRAIL NUMBER: T308

STATION: Muscatatuck NWR



Photo # 1897 - MP 0.5 - Sign

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1899 - MP 0.52 - Drainage Deficiency

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1902 - MP 0.53 - Drainage Deficiency

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1903 - MP 0.53 - Bridge

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1904 - MP 0.54 - Drainage Deficiency

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1905 - MP 0.8 - Drainage Deficiency

TRAIL NUMBER: **T308**

STATION: Muscatatuck NWR



Photo # 1906 - MP 0.82 - Drainage Deficiency

TRAIL NUMBER: **T308** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1908 - MP 0.83 - Sign

TRAIL NUMBER: T308

STATION: Muscatatuck NWR




Photo # 1909 - MP 0.84 - Sign

TRAIL NUMBER: **T308**STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1885-6 - MP 0.96 - Sign

TRAIL NUMBER: T309

STATION: Muscatatuck NWR



Photo # 1911 - MP 0.0 - Trailhead

TRAIL NUMBER: **T309**STATION: Muscatatuck NWR

DATE: 10/21/2006




Photo # 1909 - MP 0.0 - Sign

TRAIL NUMBER: T309

STATION: Muscatatuck NWR



Photo # 1910 - MP 0.0 - Sign

TRAIL NUMBER: **T309** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1913 - MP 0.01 - Erosion Deficiency

TRAIL NUMBER: **T309**

STATION: Muscatatuck NWR



Photo # 1914 - MP 0.03 - Drainage Deficiency

TRAIL NUMBER: **T309** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1915 - MP 0.08 - Sign

TRAIL NUMBER: **T309**

STATION: Muscatatuck NWR



Photo # 1916 - MP 0.08 - Begin Section 002

TRAIL NUMBER: **T309** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1918 - MP 0.23 - Drainage Deficiency

TRAIL NUMBER: **T309**

STATION: Muscatatuck NWR



Photo # 1919 - MP 0.25 - Drainage Deficiency

TRAIL NUMBER: **T500** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 0997 - MP 0.0 - Trailhead, Sign

TRAIL NUMBER: **T500**

STATION: Muscatatuck NWR



Photo # 0998 - MP 0.02 - Sign (Grouped)

TRAIL NUMBER: **T500** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1001 - MP 0.07 - Begin Section 002

TRAIL NUMBER: **T500**

STATION: Muscatatuck NWR



Photo # 1002 - MP 0.09 - Begin Section 004

TRAIL NUMBER: **T500** STATION: Muscatatuck NWR

DATE: 10/20/2006



Photo # 1000 - MP 0.12 - Begin Section 003

TRAIL NUMBER: **T501**

STATION: Muscatatuck NWR



Photo # 1088 - MP 0.0 - Trailhead

TRAIL NUMBER: **T501** STATION: Muscatatuck NWR

DATE: 10/21/2006



Photo # 1087 - MP 0.0 - Sign

TRAIL NUMBER: **T501**

STATION: Muscatatuck NWR



Photo # 1089 - MP 0.07 - Begin Section 002

The Trail Inventory of Patoka River National Wildlife Refuge Oakland City, Indiana





Prepared By: Federal Highway Administration Central Federal Lands Highway Division October 2006



Patoka River NWR Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

		Mileage by Trail Condition								Total			
Trail Surface	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	lated*	Miles
Туре	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
Native	0.22	21%		0%		0%		0%		0%		0%	0.22
Gravel	0.20	19%		0%		0%		0%		0%		0%	0.20
Asphalt		0%		0%		0%		0%		0%		0%	0.00
Concrete		0%		0%		0%		0%		0%		0%	0.00
Turnpike		0%		0%		0%		0%		0%		0%	0.00
Boardwalk	0.03	3%		0%		0%		0%		0%		0%	0.03
Puncheon		0%		0%		0%		0%		0%		0%	0.00
Woodchips		0%		0%		0%		0%		0%		0%	0.00
Mowed	0.22	21%		0%	0.40	37%		0%		0%		0%	0.62
Admin Road		0%		0%		0%		0%		0%		0%	0.00
Other		0%		0%	·	0%		0%		0%		0%	0.00
Totals	0.67	63%	0.00	0%	0.40	37%	0.00	0%	0.00	0%	0.00	0%	1.07

Trail Miles and Percentages by Trail Classification and Condition

Trail		Mileage by Trail Condition									Total		
Classificatio	Exce	ellent	Go	od	Fa	air	Po	oor	Very	Poor	Not R	lated*	Miles
n	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	MILES	%	IVIIICS
TC1		0%		0%		0%		0%		0%		0%	0.00
TC2	0.02	2%		0%		0%		0%		0%		0%	0.02
TC3	0.62	58%		0%	0.40	37%		0%		0%		0%	1.02
TC4		0%		0%		0%		0%		0%		0%	0.00
TC5	0.03	3%		0%		0%		0%		0%		0%	0.03
Totals	0.67	63%	0.00	0%	0.40	37%	0.00	0%	0.00	0%	0.00	0%	1.07


^{*} Admin Roads are included in the inventory but are not rated for condition.

Trail Features

Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T300	Sign	1	No	0.00	0978
T300	Boardwalk -If	70	No	0.11	0980
T301	Sign	2	No	0.00	0985
T301	Gate	1	No	0.00	N/A
T301	Culvert -If	8	No	0.25	N/A
T302	Sign	1	No	0.00	0993
T302	Bridge -sf	125	No	0.23	0995

sf-square feet If-linear feet cf-cubic feet

PATOKA RIVER NATIONAL WILDLIFE REFUGE TRAIL LOCATION MAP








TRAILS ID

Org. Code: 31560

Station Name: Patoka River NWR

Trail #	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Hugh Boyd Trail	Gravel	10054283	0.2	From Parking Lot (Rte 905) to end of trail loop
T301	Bird Trail	Mowed	10055145	0.62	From Parking Lot (Rte 905) to end of trail loop
T302	South Fork Fishing Trail	Native, Boardwalk	10054284	0.25	From Parking Lot (Rte 900) to end of trail

TRAIL CONDITION



Trail Name: Hugh Boyd Trail Refuge Name: Patoka River NWR

Trail Number: T300 Region: 3 TOTAL LENGTH: 0.2 Miles Section Number 001 Section Length (miles) 0.2 SAMMS Number 10054283

10/20/2006

Trail Section Information

Rating Date


Trail Class TC3 Surface Type Gravel Surface Firmness Firm Width (inches) 55 Average Grade (%) 5.8 Average X-slope (%) 7.4 Trail Condition Information **Deferred Maintenance** \$0

CRV \$26000 **FCI** 0 Condition Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$0	\$26000	0	Excellent

TRAIL CONDITION



Trail Name: Bird Trail Refuge Name: Patoka River NWR


Trail Number: T301 Region: 3 TOTAL LENGTH: 0.62 Mile

Hall Hulliber. 1501		Region. 3		TOTAL LENG	STH: 0.62 Miles
Section Number	001	002	003	004	
Section Length (miles)	0.4	0.08	0.12	0.02	
SAMMS Number	10055145	10055145	10055145	10055145	
Rating Date	10/20/2006	10/20/2006	10/20/2006	10/20/2006	
Trail Section Information					
Trail Class	TC3	TC3	TC3	TC3	
Surface Type	Mowed	Mowed	Mowed	Mowed	
Surface Firmness	Firm	Firm	Firm	Firm	
Width (inches)	80	80	65	60	
Average Grade (%)	3.6	3.6	3.6	3.6	
Average X-slope (%)	3.5	3.5	3.5	3.5	
Trail Condition Information					
Deferred Maintenance	\$1700	\$0	\$0	\$0	
CRV	\$17700	\$2900	\$3700	\$600	
FCI	0.096	0	0	0	
Condition	Fair	Excellent	Excellent	Excellent	

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$1700	\$24900	0.068	Fair

TRAIL DEFICIENCY




Trail Name: Bird Trail Refuge Name: Patoka River NWR

Trail Number: T301 Region: 3 TOTAL LENGTH: 0.62 Miles

Mile Post	0.25	0.25	
Section Number	001	001	
Photo Number	0987	0987	
Deficiency	Drainage	Drainage	
Action	Build/Add	Build/Add	
Item	Culvert -If	Tread -sf	
Quantity	15	80	
Deferred Maintenance	\$1600	\$100	
		1	

TRAIL CONDITION



Trail Name: South Fork Fishing Trail Refuge Name: Patoka River NWR

Trail Number: T302 Region: 3 TOTAL LENGTH: 0.25 Miles

				TOTAL LENG	
Section Number	001	002	003		
Section Length (miles)	0.2	0.03	0.02		
SAMMS Number	10054284	10054284	10054284		
Rating Date	10/20/2006	10/20/2006	10/20/2006		
Trail Section Information					
Trail Class	TC3	TC5	TC2		
Surface Type	Native	Boardwalk	Native		
Surface Firmness	Firm	Hard	Firm		
Width (inches)	90	72	24		
Average Grade (%)	2.3	2.3	2.3		
Average X-slope (%)	3.7	3.7	3.7		
Trail Condition Information					
Deferred Maintenance	\$0	\$0	\$0		
CRV	\$34400	\$28300	\$1000		
FCI	0	0	0		
Condition	Excellent	Excellent	Excellent		

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
\$0	\$63700	0	Excellent

TRAIL NUMBER: **T300** STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0979 - MP 0.0 - Trailhead

TRAIL NUMBER: **T300**

STATION: Patoka River NWR



Photo # 0978 - MP 0.0 - Sign

TRAIL NUMBER: **T300**

STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0980 - MP 0.11 - Boardwalk

TRAIL NUMBER: **T301**

STATION: Patoka River NWR



Photo # 0986 - MP 0.0 - Trailhead

TRAIL NUMBER: T301

STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0985 - MP 0.0 - Sign

TRAIL NUMBER: **T301**

STATION: Patoka River NWR



Photo # 0989 - MP 0.05 - Begin Section 002

TRAIL NUMBER: **T301**

STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0992 - MP 0.07 - Begin Section 004

TRAIL NUMBER: **T301**

STATION: Patoka River NWR



Photo # 0991 - MP 0.08 - Begin Section 003

TRAIL NUMBER: **T301**

STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0987 - MP 0.25 - Drainage Deficiency, Drainage Deficiency

TRAIL NUMBER: **T302**

STATION: Patoka River NWR



Photo # 0993 - MP 0.0 - Trailhead, Sign

TRAIL NUMBER: **T302**

STATION: Patoka River NWR

DATE: 10/20/2006



Photo # 0994 - MP 0.2 - Begin Section 002

TRAIL NUMBER: **T302**

STATION: Patoka River NWR



Photo # 0995 - MP 0.23 - Bridge

TRAIL NUMBER: **T302**

STATION: Patoka River NWR



Photo # 0996 - MP 0.23 - Begin Section 003

APPENDIX

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS Asset number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .011 - .05 = Good FCI .051 - .10 = Fair FCI .11 - .20 = Poor

FCI > -.20 = Very Poor

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

Elem ID

Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped Features Grouped features include non-unique signs (mileposts,

interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity" field of the data dictionary. CRV for grouped features are included in whatever trail section the GPS point was

taken.

Info Type Type of accessibility information available at trailhead:

brochure, sign or other.

Item on which the "Action" (see above) will be

performed.

Manage_Use Managed use of the trail: HIKE, BIKE, NSPC (non-

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

Max Grade Maximum grade (in percent) of trail. Only collected for

Trail Classes 4 and 5 and when > 10%.

Min Width Minimum Width (inches) of trail. Only collected for

Trail Classes 4 and 5.

MP (**Milepost**) Distance, in miles, of a trail feature or deficiency from

the Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail

Structure

Boardwalk, Turnpike, Puncheon.

SAMMS No Asset Number

Station Boundary Approved Acquisition Boundary files downloaded from

FWS website.

T Class Trail Class: TC1-5 (see Trail Classification System for

descriptions).

Tr Desig Trail Designation: Standard (Std), National Historic Trail

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Trail NoTrails are numbered based on Trail Class at the trailhead.

TC 1 = T100 series, TC2 = T200 series, etc.

Turnpike Trail tread elevated with dirt, rock or other aggregate

from parallel side ditches and held in place by logs.

National Trail Data Standards USD







Trail Classification

Trail Attributes	Trail Class 1 Minimal/Undeveloped Trail	Trail Class 2 Simple/Minor Development Trail	Trail Class 3 Developed/Improved Trail	Trail Class 4 Highly Developed Trail	Trail Class 5 Fully Developed Trail
	Physi		eral Criteria oplied to All National Forest S	Sytem Trails	
Tread & Traffic Flow	Tread intermittent and often indistinct May require route finding Native materials only	Tread discernible and continuous, but narrow and rough Few or no allowances constructed for passing Native materials	Tread obvious and continuous Width accommodates unhindered one-lane travel (occasional allowances constructed for passing) Typically native materials	Tread wide and reltively smooth with few irregularities Width may consistently accommodate two-lane travel Native or imported materials May be hardened	*Width generally accommodates two-lane and two-directional travel, or provides frequent passing turnouts *Commonly hardened with asphalt or other imported material
Obstacles	Obstacles common Narrow passages; brush, steep grades, rocks and logs present	Obstacles occasionally present Blockages cleared to define route and protect resources Vegetation may encroach into trailway	Obstacles infrequent Vegetation cleared outside of trailway	Few or no obstacles exist Grades typically <12% Vegetation cleared outside of trailway	No obstacles Grades typically <8%
Constructed Features & Trail Elements	Minimal to non- existent Drainage is functional No constructed bridges or foot crossings	Structures are of limited size, scale, and number Drainage functional Structures adequate to protect trail infrastructure and resources Primitive foot crossings and fords	Trail structures (walls, steps, drainage, raised trail) may be common and substantial Trail bridges as needed for resource protection and appropriate access Generally native materials used in Wilderness	Structures frequent and substantial Substantial trail bridges are appropriate at water crossings Trailside amenities may be present	Structures frequent or continuous; may include curbs, handrails, trailside amenities, and boardwalks Drainage structures frequent; may include culverts and road-like designs
Signs	Minimum required Generally limited to regulation and resource protection No destination signs present	Minimum required for basic direction Generally limited to regulation and resource protection Typically very few or no destination signs present	Regulation, resource protection, user reassurance Directional signs at junctions, or when confusion is likely Destination signs typically present Informational and interpretive signs may be present outside of Wilderness	*Wide variety of signs likely present *Informational signs likely (outside of Wilderness) *Interpretive signs possible (outside of Wilderness) *Trail Universal Access information likely displayed at trailhead	*Wide variety of signage is present *Information and interpretive signs likely *Trail Universal Access information is typically displayed at trailhead *
Typical Recreation Environs & Experience ²	Natural, unmodified ROS: Often Primitive setting, but may occur in other ROS settings WROS: Primitive	Natural, essentially unmodified ROS: Typically Semi-Primitive setting WROS: Primitive to Semi-Primitive	Natural, primarily unmodified ROS: Typically Semi-Primitive to Roaded Natural setting WROS: Semi-Primitive to Transition	*May be modified *ROS: Typically Roaded Natural to Rural setting *WROS: Transition (rarely present in Wilderness)	Can be highly modified ROS: Typically Rural to Urban setting Commonly associated with Visitor Centers or high-use recreation sites Not present in Wilderness

Note: Trail Class descriptions define "typical" attributes, and exceptions may occur for any attribute.